EXAMGOOD

QUESTION & ANSWER

Exam Good provides update free of charge in one year!

Accurate study guides

High passing rate!

Exam : **API-580**

Title : Risk Based Inspection Professional

Version : DEMO

1.The data validation step stresses the need for a knowledgeable individual.

A. To comparing data from the inspections to the expected deterioration mechanism and rates

B. To compare the results with previous measurements on that system

C. Similar systems at the site or within the company or published data

D. All of the above

Answer: D

2.Following are the critical variables for deterioration mechanism except

A. Material of construction

B. Process operating

C. Start up and shut down conditions

D. Insulation

Answer: D

3.If a qra has been prepared for a process unit, the analysis can borrow extensively from this effort.

A. Rbi consequence

B. Rbi likelihood

C. Rbi probability

Answer: C

4.If the probability and consequence combination (risk) is high enough to be unacceptable, then

A. A mitigation action to predict or prevent the eventis recommended.

B. A mitigation action to predict or prevent the event isnot recommended

C. Warrant to analyze risks involved

Answer: A

5.A Rbi analysis shares many of the techniques and data requirements with a_____.

A. Qra

B. Pha

C. Hazop

D. Event tree

Answer: A