

EXAMGOOD

QUESTION & ANSWER

Exam Good provides update free of charge in one year!

Accurate study guides
High passing rate!

<http://www.examgood.com>

Exam : **922-096**

Title : Comm.Server 1000 RIs.5.0
Branch Office Install &
Comm.

Version : DEMO

1. The Branch Office platform includes a Media Gateway (MG) 1000B Core connected to a Communication Server 1000 RIs. 5.0 system at the main office over a LAN or a WAN. This configuration enables a secondary location to centralize the call processing of its IP-based communication network. Which statement is a true about the deployment of the MG 1000B?

- A. It must be distributed in pairs.
- B. It can be configured for survivability.
- C. It can be distributed across a multiple building IP network.
- D. It must be co-located with the Call Servers within a building.

Answer: C

2. In a Communication Server (CS) 1000 RIs. 5.0 Branch Office solution, which hardware component is required to host the Network Routing Service (NRS) software?

- A. Call Server
- B. Signaling Server
- C. MRV Terminal Server
- D. Media Gateway Controller (MGC)

Answer: B

3. When implementing a Communication Server (CS) 1000 RIs. 5.0 Branch Office solution, which hardware component is required to control call processing and provide the system memory required to store operating software and customer data?

- A. SSC card
- B. shared media hub
- C. CP-PM Call Server
- D. MRV Terminal Server

Answer: C

4. A customer is implementing a Communication Server (CS) 1000 RIs. 5.0 Branch Office solution. The customer wants to know if there are any special package requirements beyond the base CS 1000 RIs. 5.0 software? Which software package is mandatory when deploying a CS 1000 RIs. 5.0 Branch Office?

- A. Branch Media Gateway package 390
- B. Network Signaling (NSIG) package 37

C. Network Alternate Route Selection (NARS) package 58

D. SIP Gateway and Converged Desktop (SIP) package 406

Answer:A

5. A customer recently deployed a Communication Server (CS) 1000 RIs. 5.0 Branch Office solution. When examining the Call Server database of the main office, you observe that the bandwidth management zone created for the Branch Office on the main office is the same number as the zone created on the Branch Office. Which programming change will you recommend?

A. Add a new bandwidth management zone, zone 0, on the main office.

B. Make no changes to the main office or branch office zone numbering scheme.

C. Change the zone number on the main office to prevent potential conflicts with the branch office.

D. Change the zone number on the branch office to prevent potential conflicts with the main office.

Answer: B