EXAMGOOD QUESTION & ANSWER

Exam Good provides update free of charge in one year!

Accurate study guides High passing rate!

http://www.examgood.com

Exam : HP2-T26

Title : Servicing HP BladeSystem Solutions

Version : Demo

1.You want to add memory to an existing BL890c i2 server. The new DIMMs have a different size than the installed ones.

Which memory upgrade guideline is correct?

A. Distribute old and new memory evenly on all blade modules, installing the larger ones first.

B. Blade modules 1 and 2 must have one DIMM size, and blade modules 3 and 4 must have the other DIMM size.

C. Blade modules 1 and 3 must have one DIMM size, and blade modules 2 and 4 must have the other DIMM size.

D. Distribute old and new memory evenly on all blademodules, installing the smallerones first.

Answer: A

2.Your Virtual Connect firmware is older than 1.34.

What is the recommended upgrade order for the components in a c7000 enclosure?

- A. Onboard Administrators, Blades, Virtual Connect
- B. Virtual Connect, Blades, Onboard Administrators
- C. Virtual Connect, Onboard Administrators, Blades
- D. Blades, Virtual Connect, Onboard Administrators

Answer: A

3.Why is it considered a best practice to use tools such as HP Smart Update Manager (SUM) and Virtual Connect Support Utility (VCSU) to deploy firmware components?

- A. These tools check the dependencies and limitations.
- B. The tools are compatible with all versions of firmware.
- C. These are the only tools that can be used to work with Virtual Connect Enterprise Utility (VCEU).
- D. These tools are version compatible by design.

Answer: A

4. What should a support engineer use to perform a firmware update to a c-Class PCI Expansion Blade?

- A. OA CLI
- B. HP SmartStart
- C. Firmware Maintenance DVD
- D. OA GUI

Answer: A

5.Which Windows command allows you to see the operating system version and system name, manufacturer, and model?

- A. msconfig
- B. uname
- C. msinfo32
- D. winver

Answer: C

6.Which Windows commands allow you to get the operating system's version, build, and service patch level? (Select two.)

- A. winver
- B. msconfig
- C. patch
- D. msinfo32
- E. swlist
- F. uname

Answer: B,D

7.Which command should you use to connect to the CLI interface of an HP ProCurve Blade Switch through the Onboard Administrator?

- A. connect interconnect <bay_number>
- B. connect switch <bay_number>
- C. connect <bay_number>
- D. connect server <bay_number>

Answer: A

8.A user added a second OA to a c7000 enclosure so the OAs are redundant, however, the modules are not at the same firmware level.

What is an easy way to bring them to the same firmware version?

- A. Use HP SUM to update each OA individually.
- B. Request that the Admin have SIM push the updates to the each OA.

C. Use HP SUM Offline to update the standby OA, restart it, and repeat the procedure on the remaining OA.

D. Select the Synchronize Firmware button in either OA.

Answer: D

9. Which tool can be used to upgrade the firmware of Virtual Connect Ethernet module? (Select two.)

- A. HP SUM
- B. OA
- C. VCSU
- D. VCEM
- E. HP SIM

Answer: A,C

10. Which tool can be used to verify that SNMP events appear in HP SIM from a blade server running Windows 2008?

- A. Onboard Administrator
- B. System Management Homepage
- C. HP SNMP Agent
- D. Integrated Lights-Out

Answer: B

11. How should you save a Virtual Connect configuration?

A. from CLI: show all > cfg.txt

- B. enclosure setting, configuration scripts, inventory
- C. enclosure setting, configuration scripts, show config, save
- D. domain setting, backup/restore

Answer: D

12.Which iLO3 MP logs should be looked at to check the hardware status of an HP Integrity BL870c i2 Server Blade? (Select two.)

- A. Syslog log
- B. System Event log
- C. Forward Progress log
- D. Machine Check log
- E. Resource Monitor log
- Answer: B,C

13. Which feature should you enable in RBSU in a G7 server to reduce processor power usage and improve overall performance in some applications?

- A. Intel Hyperthreading Options
- B. HP Dynamic Power Savings Mode
- C. Processor Core Disable
- D. HP Static Low Power Mode
- E. OS Control Mode

Answer: C

14.What is used to update firmware on several HP VC Ethernet or Fibre Channel modules simultaneously?

- A. VCM
- B. HP FDT
- C. VCSU
- D. OA

Answer: C

15.What is a DDR3 Memory population rule to follow for Gen8 servers?

- A. If only one processor is installed in a two processor system, only half of the DIMM slots are available.
- B. DIMMs of different voltages cannot be mixed in the same bank.
- C. DIMMs of different speed grades can be mixed.
- D. UDIMMs, RDIMMs, or LRDIMMs can be mixed.

Answer: A

16.What is the advantage of Solid State Drive over I/O Accelerator?

- A. It offers higher reliability.
- B. It is bootable.
- C. It has a longer life span.
- D. It has higher throughput.

Answer: B

17. Which memory configuration types are supported in the Gen8 ProLiant Blade servers? (Select two.)

- A. DDR2
- B. SODIMM
- C. SDIMM
- D. RDIMM
- E. UDIMM

Answer: D,E

18.Your customer has a business critical HP BladeSystem enclosure and wants to protect it with additional service coverage. The company's requirements are 24x7 and functionality must be restored within a defined time.

Which HP Service offering is needed to fulfill the customer's requirements?

- A. HP Critical Advantage L3
- B. HP Proactive Select 30 Credit
- C. HP 6 hour Hardware Support Onsite Call-to-Repair Service
- D. HP 24x7 hour Response, Hardware Support Onsite Service

Answer: C

19. Which benefit is provided by having identical Interconnect modules in adjacent bays of the c7000 enclosure?

- A. reduced power requirements
- B. dynamic IO bandwidth
- C. improved uplink failure detection
- D. redundant IO capabilities

Answer: D

20.HP standard warranties support the HP hardware.

What are HP Care Packs designed to support?

- A. Software
- B. Network
- C. Storage
- D. Business
- Answer: A